™:≅ 25X1	O659Z 11 APR 60 SECRET	2 3 5 5 5 6 RT		
energia en	DIRECTOR			
PROM			n de antier de georgen on Rem en gester	
action.	DPD (1,2,3,4,5,6,7,8,9,10)	ROUTINE		
HEFO.	S/C (11)			
25.74	RLU			
25X1	TOR: 0659Z 11 APR 60	() IN-22775		
a de la composição de l	CIVE CONTRACTOR OF THE CONTRAC	THE EST		
25X1	1. SWC 240 FROM		5X1	
	2. ARTICLE 343, J-57-31A, P-607373, TOTAL TIME: 467:55. NO 25X1			
	MISSIONS THIS PERIOD.			
	3. ARTICLE 349, J-57-31A: P-607867, TOTA	L TIME, 126:50. THIS		
	ARTICLE MADE A FORCE LANDING DUE TO FUEL STARVATION 5 APRIL, RETURNING			
	FROM MISSION NUMBER 5 BECAUSE THE DRIVER WAS	UNABLE TO LOCATE THE		
	STAGING AREA AND EXHAUSTED HIS FUEL SUPPLY.	ARTICLE IS BEING		
: :	RECOVERED, PRESENT REPORTS INDICATE ARTICLE	AND ENGINE WILL BE		
5X1	RETURNED TO ENGINE APPARENTLY NOT	INVOLVED. MISSIONS		
: : !	PREVIOUS TO FORCE LANDING:			
	A. GO NUMBER 3, 29 MARCH 1960 TO	FLIGHT TIME: 6:50	25>	
	HOURS, FERRY TO STAGING AREA, NO ENGINE PROB	LEMS.		
	B. GO NUMBER 4, 31 MARCH 1960 TO	FLIGHT TIME: 9:30	25>	
	HOURS, NO ENGINE PROBLEMS.			
	C. GO NUMBER 5, 5 APRIL 1960 TO	TIME: 9:50 HOURS	25>	
	WHEN EXHAUSTED FUEL AND LANDED STILL INVESTIG			
	4. ARTICLE 352, J-75-13, P-610451, TOTAL			
	The state of the s	The second of the second secon	٨	

sih

25X1

SECRET

(IN-22775)		PAGE TWO		
_	22, 29 MARCH 1960 TO	FLIGHT TIME: 7:55 TO STAGING AREA.	25X1	
	10 NUMBER 23, 31 MARCH 1960 TO	FLIGHT TIME: 10:20.	25X1	
	TO NUMBER 24, 6 APRIL 1960 TO	FLIGHT TIME: 6:45 RETURN	25X1	
•	TO THIS AREA. NO ENGINE PROBLE	EMS.		
	5. SPARE ENGINE: YJ-57-31/	, P-605917, TOTAL TIME: 232:15.		
		IND OF MESSAGE	Y	

gih